FIG.1




FIG.2




FIG.3






FIG.4



## FIG.5

VERTEX X	VERTEX Y	VERTEX Z	NORMAL X	NORMAL Y	NORMAL Z
SURFACE ①					
-0.250.	0.375.	1.000.	-0.50,	0.75.	0.00
0.250.	0.375.	1.000.	0.50.	0.75.	0.00
0.250,	0.375.	0.000.	0, 50.	0.75,	0.00
-0.250,	0.375.	0.000.	-0.50.	0.75,	0.00
SURFACE ②	,	,	0. 00,	0.1.0,	0.00
0. 250.	0.375,	1.000.	0.50.	0.75,	0.00
0.500.	0.000.	1.000,	1.00,	0.00.	0.00
0.500,	0.000,	0.000,	1.00,	0.00,	0.00
0.250,	0.375.	0.000,	0. 50.	0.75,	0.00
SURFACE (3)	0.070,	0.000,	0. 00,	0.10,	0.00
0.500.	0.000.	1.000,	1.00,	0.00.	0.00
0, 250,	-0.375,	1.000.	0.50,	-0.75,	0.00
0.250,	-0.375,	0.000.	0.50.	-0.75	0.00
0.500,	0.000,	0.000,	1.00.	0.00.	0.00
SURFACE @	0.000,	0. 000,	1.00,	0.00,	4.00
0. 250.	-0.375.	1.000.	0, 50,	-0.75.	0.00
-0.250,	-0.375.	1.000,	-0.50,	-0.75.	0.00
-0.250.	-0.375.	0.000,	-0.50,	-0.75.	0.00
0.250.	-0.375.	0.000,	0.50.	-0.75,	0.00
SURFACE (5)	0.010,	0.000,	4. 50,	0.10,	0.00
-0.250.	-0.375.	1.000.	-0.50.	-0.75.	0.00
-0.500,	0.000,	1.000,	-1, 00,	0.00,	0.00
-0.500.	0.000,	0.000,	-1.00,	0.00,	0.00
-0.250.	-0.375,	0.000,	-0.50,	-0.75.	0.00
SURFACE ®	,	0.000,	0.00,	31.5,	4.00
-0.500.	0.000.	1.000.	-1.00.	0.00.	0.00
-0.250,	0.375,	1.000,	-0.50,	0.75,	0.00
-0.250,	0.375,	0.000,	-0.50,	0.75,	0.00
-0.500,	0.000,	0.000,	-1.00.	0.00.	0.00
5. 500,	5.000,	3.300,	,. 00,	J. 00,	0.00






FIG.8




FIG.9A




FIG.9B






FIG.11

